NASA/TM-2009-215570 NESC-RP-05-114/05-013-E





Kennedy Space Center (KSC) Launch Complex 39 (LC-39) Gaseous Hydrogen (GH₂) Vent Arm Behavior Prediction Model Review Technical Assessment Report

Timmy R. Wilson/NESC Kennedy Space Center, Kennedy Space Center, Florida

Geoffrey Beech and Ian Johnston Marshall Space Flight Center, Huntsville, Alabama

NASA STI Program . . . in Profile

Since its founding, NASA has been dedicated to the advancement of aeronautics and space science. The NASA scientific and technical information (STI) program plays a key part in helping NASA maintain this important role.

The NASA STI program operates under the auspices of the Agency Chief Information Officer. It collects, organizes, provides for archiving, and disseminates NASA's STI. The NASA STI program provides access to the NASA Aeronautics and Space Database and its public interface, the NASA Technical Report Server, thus providing one of the largest collections of aeronautical and space science STI in the world. Results are published in both non-NASA channels and by NASA in the NASA STI Report Series, which includes the following report types:

- TECHNICAL PUBLICATION. Reports of completed research or a major significant phase of research that present the results of NASA programs and include extensive data or theoretical analysis. Includes compilations of significant scientific and technical data and information deemed to be of continuing reference value. NASA counterpart of peer-reviewed formal professional papers, but having less stringent limitations on manuscript length and extent of graphic presentations.
- TECHNICAL MEMORANDUM. Scientific and technical findings that are preliminary or of specialized interest, e.g., quick release reports, working papers, and bibliographies that contain minimal annotation. Does not contain extensive analysis.
- CONTRACTOR REPORT. Scientific and technical findings by NASA-sponsored contractors and grantees.

- CONFERENCE PUBLICATION. Collected papers from scientific and technical conferences, symposia, seminars, or other meetings sponsored or co-sponsored by NASA.
- SPECIAL PUBLICATION. Scientific, technical, or historical information from NASA programs, projects, and missions, often concerned with subjects having substantial public interest.
- TECHNICAL TRANSLATION. Englishlanguage translations of foreign scientific and technical material pertinent to NASA's mission.

Specialized services also include creating custom thesauri, building customized databases, and organizing and publishing research results.

For more information about the NASA STI program, see the following:

- Access the NASA STI program home page at <u>http://www.sti.nasa.gov</u>
- E-mail your question via the Internet to help@sti.nasa.gov
- Fax your question to the NASA STI Help Desk at 443-757-5803
- Phone the NASA STI Help Desk at 443-757-5802
- Write to: NASA STI Help Desk NASA Center for AeroSpace Information 7115 Standard Drive Hanover, MD 21076-1320

NASA/TM-2009-215570 NESC-RP-05-114/05-013-E





Kennedy Space Center (KSC) Launch Complex 39 (LC-39) Gaseous Hydrogen (GH₂) Vent Arm Behavior Prediction Model Review Technical Assessment Report

Timmy R. Wilson/NESC Kennedy Space Center, Kennedy Space Center, Florida

Geoffrey Beech and Ian Johnston Marshall Space Flight Center, Huntsville, Alabama

National Aeronautics and Space Administration

Langley Research Center Hampton, Virginia 23681-2199

The use of trademarks or names of manufacturers in the report is for accurate reporting and does not
constitute an official endorsement, either expressed or implied, of such products or manufacturers by the National Aeronautics and Space Administration.
Available from:
NASA Center for AeroSpace Information

NASA Center for AeroSpace Information 7115 Standard Drive Hanover, MD 21076-1320 443-757-5802

Toma Turney	Technical Assessment Report	RP-05-114	1.0
Kennedy Space Center (KSC) Launch Complex 39 (LC-39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior Prediction Model Review Technical Assessment Report		Page #: 1 of 32	

Kennedy Space Center (KSC) Launch Complex 39 (LC-39) Gaseous Hydrogen (GH₂) Vent Arm Behavior Prediction Model Review

Technical Assessment Report

October 6, 2005

NASA Engineering and Safety Center Technical Assessment Report Title: Kennedy Space Center (KSC) Launch Complex 39 (LC-39) Gaseous Hydrogen (GH₂) Vent Arm Behavior Prediction Model Review Technical Assessment Report

TABLE OF CONTENTS

Volume I: Technical Assessment Report

1.0	Authorization and Notification	3
2.0	Signature Page	4
3.0	Team Members, Ex Officio Members, and Consultants	5
4.0	Executive Summary	6
5.0	Assessment	7
6.0	Description of the Problem, Proposed Solutions, and Risk Assessment	
7.0	Data Analysis	12 12
8.0	7.3 Stiffness Verification Findings, Observations and Recommendations 8.1 Findings 8.2 Recommendations	1 7
9.0	Lessons Learned	18
10.0	Definition of Terms	18
11.0	Minority Report (Dissenting Opinions)	18
Appe Appe Appe	me II: Appendices ndix A. ITA/I Request Form (NESC-PR-003-FM-01) ndix B. Vent Pipe Sensitivities ndix C. Pictures of the FE Model and the Associated Calculations ndix D. List of Acronyms	24 27
	<u>List of Figures</u>	
6.0-1 6.0-2 6.0-3	Tank Vent Umbilical Retraction Mechanism Static Lanyard Drop-Weight Function Umbilical Retention Mechanism	10

TO THE PARTY OF TH	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0
Title:			Page #:
Kenn	edy Space Center (KSC) Launch Complex	39 (LC-	3 of 32
39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior			
Prediction Model Review Technical Assessment Report			

Volume I: Technical Assessment Report

1.0 Authorization and Notification

The request to conduct an independent technical assessment (ITA) was submitted to the NASA Engineering and Safety Center (NESC) on March 29, 2005.

Mr. Ralph Roe, Director of the NESC, approved this activity in an out-of-board action on April 4, 2005.

The ITA Plan was developed by Timmy R. Wilson and approved in an out-of-board action by the NESC Review Board (NRB) on May 5, 2005. Follow-up updates to the Plan were approved by the NRB on May 12, 2005.

The NESC team review of the Kennedy Space Center (KSC) Launch Complex 39 (LC-39) math model took place between April 28, 2005 and July 27, 2005.

The final Technical Assessment report was presented to the NRB on October 6, 2005.

	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0
Kennedy Space Center (KSC) Launch Complex 39 (LC-		Page #: 4 of 32	
39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior Prediction Model Review Technical Assessment Report			

2.0 Signature Page

Assessment Team Members

Timmy R. Wilson	Geoffrey Beech
NESC Chief Engineer, KSC Lead	Systems Analysis Team Lead, MSFC
Ian Johnston, MSFC Structural and Dynamics Analysis Branch, MSFC	

TO SERVICE SER	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0
Kennedy Space Center (KSC) Launch Complex 39 (LC-39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior Prediction Model Review Technical Assessment Report		Page #: 5 of 32	

3.0 Team Members, Ex Officio Members, and Consultants

Timmy R. Wilson, NESC Chief Engineer (NCE) Geoffrey Beech, MSFC Ian Johnston, MSFC

TO THE PARTY OF TH	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0
Title:			Page #:
Kennedy Space Center (KSC) Launch Complex 39 (LC-			6 of 32
39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior			
Prediction Model Review Technical Assessment Report			

4.0 Executive Summary

The NESC Assessment Team reviewed a computer simulation of the LC-39 External Tank (ET) GH₂ Vent Umbilical system developed by United Space Alliance (USA) for the Space Shuttle Program (SSP) and designated KSC Analytical Tool ID 451 (KSC AT-451). The team verified that the vent arm kinematics were correctly modeled, but noted that there were relevant system sensitivities. Also, the structural stiffness used in the math model varied somewhat from the analytic calculations. Results of the NESC assessment were communicated to the model developers.

Two significant issues were identified, as follows:

- 1. The wind environment at the vent arm is not directly measured, but is estimated from data taken at remote locations.
- 2. The model is not fully validated.

It is recommended that the wind measurement equipment at LC-39 Pads A and B be upgraded to better characterize the wind speed and direction at the vent arm, and additional tests be performed to validate the model.

TO STATE OF THE PARTY OF THE PA	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0
Title:			Page #:
Kennedy Space Center (KSC) Launch Complex 39 (LC-			7 of 32
39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior			
Prediction Model Review Technical Assessment Report			

5.0 Assessment

The scope of this assessment was limited to examining and peer reviewing the GH_2 vent line math model. A plan for this effort was completed and approved by the NRB on May 12, 2005.

10	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0
l	edy Space Center (KSC) Launch Complex Gaseous Hydrogen (GH2) Vent Arm Beh	`	Page #: 8 of 32
Predi	ction Model Review Technical Assessment	t Report	

6.0 Description of the Problem, Proposed Solutions, and Risk Assessment

The GH₂ vent arm is a pad structure designed to support the Ground Umbilical Carrier Panel (GUCP) and seven-inch hydrogen vent line flex hose during the Space Shuttle pad processing (refer to Figure 6.0-1). At T-0, the GUCP separates from the Space Shuttle ET by means of a pyrotechnic device and the arm drops away from the vehicle and into a restraint (refer to Figures 6.0-2 and 6.0-3).

During the STS-108 launch (December 5, 2001), the arm failed to engage the restraining device and impacted the pad structure with resultant damage to both the arm and the pad. Debris was liberated during the incident which could have caused significant damage to the Space Shuttle flight vehicle had it made contact. Subsequent investigation identified two major contributors: a Pivot Arm shock absorber did not operate properly causing the Pivot Arm to twist and rotate the vent arm to the side as it dropped; and relatively high crosswinds (10-18 knots) during launch pushed the vent arm over.

There were other factors that were considered minor contributors. Drawing and requirements changes were implemented to ensure the pivot arm shocks are lab-tested and adjusted prior to each launch. Additionally, the openings on the Umbilical Retract Deceleration Units at both LC-39 Pads A and B were widened. Clearance on the south side of both Pads A and Pad B Deceleration Unit openings was increased by 9-1/4 inches over STS-108.

The USA-developed computer simulation, KSC AT-451, simulates the kinetics of the relevant subsystems of the ET GH₂ umbilical system when subjected to the two contributors (mentioned previously) and the initial conditions due to the Space Shuttle Main Engine (SSME) startup transient (a.k.a. "twang"). Simulations conducted using this model resulted in reduction of the vent arm wind limit, from 34 to 24 knots, specified by the SSP Launch Commit Criteria (LCC). The KSC Independent Technical Authority (ITA) and Ground Operations Chief Engineer's Office requested the NESC review the math model to ensure it was not providing overly conservative or restrictive results.

THE A PARTY OF THE	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0
Title:			Page #:
Kennedy Space Center (KSC) Launch Complex 39 (LC-			9 of 32
39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior			
Prediction Model Review Technical Assessment Report			




Figure 6.0-1. Tank Vent Umbilical Retraction Mechanism

10	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0
39	edy Space Center (KSC) Launch Complex) Gaseous Hydrogen (GH2) Vent Arm Beh ction Model Review Technical Assessmen	avior	Page #: 10 of 32




Figure 6.0-2. Static Lanyard Drop-Weight Function

To the state of th	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0		
Title:			Page #:		
Kennedy Space Center (KSC) Launch Complex 39 (LC-			11 of 32		
39	39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior				
Predi	Prediction Model Review Technical Assessment Report				




Figure 6.0-3. Umbilical Retention Mechanism

TO THE PARTY OF TH	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0			
Title:			Page #:			
Kenn	edy Space Center (KSC) Launch Complex	39 (LC-	12 of 32			
39	39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior					
Predi	Prediction Model Review Technical Assessment Report					

7.0 Data Analysis

7.1 Wind Loading

Wind force predictions on the GH₂ vent arm are extrapolated from the measured winds. Two of the most significant measurements are taken using anemometers on top of 60-foot weather towers in unobstructed areas 1,200 feet from the Pad in the northwest (NW) and southeast (SE) directions. The weather towers are in approximately the same configuration for both Pads A and B. The GH₂ vent arm is at 220 feet elevation and on the Pad, out of the free stream. Winds at the arm are not directly measured.

The wind loads are calculated using American Society of Civil Engineering (ASCE) 7-98. These loads generally are based on the cross-sectional geometry of the vent arm, and the perpendicular velocity of the wind to this cross-section. This calculated drag is proportional to the square of the wind velocity. For this reason, only high winds perpendicular to the vent pipe will yield loads that could result in an anomaly similar to STS-108. This is problematic since there is not a good correlation between the measured wind data and the wind speed at the vent arm. For this reason, it is recommended that a localized wind measurement system on the vent arm, or in close proximity on the Fixed Support System (FSS), be employed.

There are non-moving, ultrasonic type wind anemometers currently on the market at low cost that would not create a debris hazard and could be attached directly to the vent arm to accurately assess the wind speed.

7.2 Kinematics Analysis

MSFC verified the system kinematics of the ET GH₂ Vent Umbilical retraction using an independent kinematics model developed in Delmia's Envision (<u>www.delmia.com</u>). The kinematics represented in KSC AT-451 was verified to be consistent with the hardware and accurate for nominal and off-nominal situations, such as the STS-108 anomaly. Kinematics analysis at MSFC included the haunch pivot arm, trunnions/slider, vent arm, and pivot arm retraction weights and shocks.

The vent arm is guided inside the capture envelope of the Deceleration Unit by two features. First, while the vent arm is roughly horizontal, the pivot arm retraction weights center the vent arm. A cable attaches a 1,500-lb withdrawal weight to the pivot arm through a pivot, which creates equal tension (750 lb) on either side of the cable. The cable is attached to the withdrawal arm link that contacts the trunnion and leverages the cable tension. This resulting contact force

TO STORY OF THE ST	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0		
Title:			Page #:		
Kenn	edy Space Center (KSC) Launch Complex	39 (LC-	13 of 32		
39	39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior				
Predi	Prediction Model Review Technical Assessment Report				

is 1,500 lbs on the trunnion on either side of the haunch pivot arm creating a restoring moment of 2,250 ft-lbs.

The second centering force occurs when the vent arm is not parallel with slots on the pivot arm. The Haunch Pivot Arm Slots (HPAS) develop contact force between the slider block, which surround the trunnions, as the vent pipe rotates down. The slots in the haunch pivot arm are initially parallel with the vent arm pipe while the GUCP is attached to the ET (refer to Figure 7.2-1). This allows the vent arm to yaw side to side to accommodate the motion of the ET just prior to Solid Rocket Booster (SRB) ignition ("twang").





Figure 7.2-1 Haunch Pivot Arm Slots (HPAS)

The arrow indicates the contact force on the slider blocks from the retraction weights.

Once the pipe has rotated so that it is no longer parallel with the HPAS (refer to Figure 7.2-2), any clearance between with the HPAS and the slider block is initially bottomed out, and out-of-



plane excursions cause a contact force between the slider block and the top and bottom of the HPAS. This contact force bottoms-out one trunnion and drives the other trunnion up the HPAS, which will lift the retraction weights as in the first scenario. There will also be an associated vent pipe to roll along its axis, which will twist the aft flex line.

It is expected that the contact forces between the HPAS and the slider blocks vary substantially for different operational conditions and could have been very large. If the forces are large enough, the slider blocks, HPAS, and the bushings and/or bearings will be damaged. Periodic inspections and replacement of this hardware should catch visible damage, but tolerances between parts will vary. Wear and tear tolerances were reviewed subsequent to STS-108 and documented in the investigation report; this was not considered a significant factor in the anomaly.





Figure 7.2-2. The HPAS at Approximately 40 Degrees to the Vent Arm Excursions in this position will cause the vent arm to roll and bend the aft flex base.

The out-of-plane excursions of the vent pipe, as it enters the deceleration unit, are sensitive to torsional flexure of the pivot arm and to any slope in the pivot arm to slider block joint or the slider block to trunnion joint. These sensitivities are illustrated in Appendix B.



Kinematics of the MSFC model as well as the KSC AT-451 represents idealized motion and perfect surface contact between links. Uniqueness of actual parts due to the flaws in the manufacturing process, nominal and off-nominal use of the system, wear and tear on the parts, bushings and bearings, etc., will create differences between an idealized system and an actual system. These differences can be characterized through tests and then be incorporated into the computer model for improvement. If it is expected that the system changes due to wear and tear or other circumstances, then the computer model should be updated for each expected use.

Because of the system's sensitivity to torsion flexure of the pivot arm and potential clearances in the joints, it is recommended that a mechanical hanging (fish) scale be utilized to document the system stiffness on either side of the Deceleration Units of both Pads A and B (reference A-23 of KSC-5600-5969).

7.3 Stiffness Verification

MSFC independently calculated component stiffness and compared them to the values used in the KSC AT-451. The two largest components, most susceptible to flexure are the pivot arm and vent arm. The stiffness of these components is critical to predicting the performance of the ET GH₂ umbilical system in high wind conditions. As there is no validation (empirical measured) data for either these components or the performance of the system in as a whole under high wind conditions, the verification and validation of the model is incomplete.

A Finite Element (FE) model of the pivot arm was created using MSC PATRAN®. The FE model was subjected to a known torque at the cross-section corresponding to the interface of the pivot arm and pivot arm shocks. The resulting angular rotation at this cross-section provides the stiffness for the first section of the pivot arm (stiffness between hinge and shock interface location) using the formula $K = M/\theta$. This approach was then repeated by applying a torque at the trunnion location. The angular rotation at the trunnions was then used to compute the overall stiffness of the pivot arm. From the following relationship, the second section stiffness (stiffness between shock interface location and the trunnions) can be computed as: $1/K_t = 1/K_1 + 1/K_2$. These stiffnesses were then compared to those used in the KSC AT-451.

The calculated stiffnesses were 38 percent lower for the first section stiffness and 20 percent lower for the second section. This difference was discussed with Roy Burton of USA. It was stated that the pivot arm stiffness had to be adjusted by this amount to correlate drop test timing results with the model. Pictures of the FE model and the associated calculations are provided in Appendix C.

TO STORY OF THE ST	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0		
Title:			Page #:		
Kennedy Space Center (KSC) Launch Complex 39 (LC-					
39	39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior				
Predi	Prediction Model Review Technical Assessment Report				

A hand-calculated stiffness value of the vent pipe was computed using the known pipe sizes of the primary double-walled pipe. This stiffness value was approximately half of the stiffness value used in the KSC AT-451. This difference was discussed with Roy Burton/USA and resulted in the discovery of erroneous values in the KSC AT-451. The values were corrected in the model, but resulted in only minor changes in results. The hand calculations are also provided in Appendix C.

In the post flight investigation, the out-of-plane stiffness of the vent arm was measured while the vent arm was hanging vertically from the pivot arm near the Deceleration Unit. It is assumed that the pivot arm was latched in the haunch for all of these tests. While this test was performed to identify any obvious malfunctions of the system, rather than to characterize the stiffness of the system, the results are useful. These tests showed the overall system stiffness to be much less than that of any of the components discussed above (reference A-23 of KSC-5600-5969). This indicates that the overall out-of-plane system stiffness is dependent on additional factors. A mechanical hanging (fish) scale test of the system would validate the overall stiffness employed by the model.

TO STATE OF THE ST	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0		
Title:			Page #:		
Kenn	edy Space Center (KSC) Launch Complex	39 (LC-	17 of 32		
39) Gaseous Hydrogen (GH ₂) Vent Arm Beh	avior			
Predi	Prediction Model Review Technical Assessment Report				

8.0 Findings, Observations and Recommendations

8.1 Findings

While KSC AT-451 represents an exceptional effort at modeling the GH_2 vent arm kinetics, it has not been substantially validated and relies on estimated wind data, not on measurements made at the arm. The relative contribution of the pivot arm shock anomaly to the impact of the vent arm on the Deceleration Unit on STS-108 cannot be understood without further testing.

With regard specifically to lowering the LCC for wind loads, it is recommended that the LCC be lowered for future Space Shuttle missions as described in the briefing prepared by Armand Gosselin and Gary Hopkins of USA in the interest of safety and conservatism.

8.2 Recommendations

If the LCC is to be relaxed to the pre-STS-114 criteria, the Assessment Team recommends the following:

- **R-1.** Use a mechanical hanging (fish) scale to measure the flexibility of the vent arm system at horizontal, 45 degrees, and vertical. Measurements should be taken at half-inch excursion intervals for both Pads A and B, and in both NW and SE directions. This data should be used to validate the KSC AT-451.
- **R-2.** Add a wind measurement device to the vent arm structure. LCC should be based on this measurement.
- **R-3.** Add instrumentation, such as cameras, infrared, targets, etc., as necessary to ascertain the motion of the vent arm on future missions, for sustained engineering and on-going validation.

TO THE STATE OF TH	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0		
Title:			Page #:		
Kenn	edy Space Center (KSC) Launch Complex	39 (LC-	18 of 32		
39	39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior				
Predi	Prediction Model Review Technical Assessment Report				

9.0 Lessons Learned

No significant lessons-learned were generated.

10.0 Definition of Terms

Corrective Actions Changes to design processes, work instructions, workmanship practices,

training, inspections, tests, procedures, specifications, drawings, tools, equipment, facilities, resources, or material that result in preventing, minimizing, or limiting the potential for recurrence of a problem.

Finding A conclusion based on facts established during the assessment/inspection

by the investigating authority.

Lessons Learned Knowledge or understanding gained by experience. The experience may

be positive, as in a successful test or mission, or negative, as in a mishap or failure. A lesson must be significant in that it has real or assumed impact on operations; valid in that it is factually and technically correct; and applicable in that it identifies a specific design, process, or decision that reduces or limits the potential for failures and mishaps, or reinforces a

positive result.

Observation A factor, event, or circumstance identified during the

assessment/inspection that did not contribute to the problem, but if left uncorrected has the potential to cause a mishap, injury, or increase the

severity should a mishap occur.

Problem The subject of the technical assessment/inspection.

Requirement An action developed by the assessment/inspection team to correct the

cause or a deficiency identified during the investigation. The requirements

will be used in the preparation of the corrective action plan.

Root Cause Along a chain of events leading to a mishap or close call, the first causal

action or failure to act that could have been controlled systemically either

by policy/practice/procedure or individual adherence to

policy/practice/procedure.

11.0 Minority Report (Dissenting Opinions)

There were no dissenting opinions during this consultation.


	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0		
Title:		20 (T C	Page #:		
Kennedy Space Center (KSC) Launch Complex 39 (LC-			19 of 32		
39	39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior				
Predi	Prediction Model Review Technical Assessment Report				

Volume II: Appendices

- ITA/I Request Form (NESC-PR-003-FM-01) Vent Arm Sensitivities A
- В
- C **Hand Calculations**
- D List of Acronyms


10	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0		
Title:			Page #: 20 of 32		
Kennedy Space Center (KSC) Launch Complex 39 (LC-					
1 ′	39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior				
Predi	Prediction Model Review Technical Assessment Report				

Appendix A. ITA/I Request Form (NESC-PR-003-FM-01)



NASA Engineering and Safety Center Request Form			
Submit this ITA/I Request, with associated artifacts attached, to: nrbexecsec@nasa.gov , or to NRB Executive Secretary, M/S 105, NASA Langley Research Center, Hampton, VA 23681			
Section 1: NESC Review Board (NRB) Executiv	e Secretary Record of Receipt		
Received (mm/dd/yyyy h:mm am/pm) 3/28/2005 12:00 AM	Status: New	Reference #: 05-013-E	
Initiator Name: Jimmy Alexander	E-mail: jimmy.a.alexander@usa- spaceops.com	Center: KSC, UNITED SPACE ALLIANCE	
Phone: (321)-861-2156, Ext	Mail Stop:		
Short Title: GH2 Vent Arm Behavior prediction I	Model Review		
loads. Refinements done to that model recently have resulted in a decrease in allowable launch winds from 34 knots to 24 knots; i.e., in winds higher than 24 knots the GH2 vent arm may hit structure as it comes down instead of dropping into the opening of the deceleration device. An answer is needed quickly since the implication is that the LCC would need to be changed before RTF. Source (e.g. email, phone call, posted on web): email			
Type of Request: Assessment			
Proposed Need Date:			
Date forwarded to Systems Engineering Office (SEO): (mm/dd/yyyy h:mm am/pm):			
Section 2: Systems Engineering Office Screening	g		
Section 2.1 Potential ITA/I Identification			
Received by SEO: (mm/dd/yyyy h:mm am/pm): 3	3/29/2005 12:00 AM		
Potential ITA/I candidate? Yes No			
Assigned Initial Evaluator (IE):			
Date assigned (mm/dd/yyyy):			
Due date for ITA/I Screening (mm/dd/yyyy):			
Section 2.2 Non-ITA/I Action			
Requires additional NESC action (non-ITA/I)?	Yes No		
If yes:			
Description of action: There is no initial evaluation required this was approved Out-of-Board to proceed with Tim Wilson leading. This is fast turn-around, review, with Tim Wilson to present the results as a position paper to the NRB for close-out			
Actionee: Tim Wilson			
Is follow-up required? ⊠Yes ☐ No If ye	s: Due Date: 4/28/2005		
Follow-up status/date:			
If no:			
NESC Director Concurrence (signature):			
Request closure date: .			

NESC Request Form NESC-PR-003-FM-01, v1.0



ection 3: Initial Evaluation			
eceived by IE: (mm/dd/yyyy h:mm am/pm):			
creening complete date:			
alid ITA/I candidate? Yes No			
nitial Evaluation Report #: NESC-PN-			
arget NRB Review Date:			
ection 4: NRB Review and Disposition of NCE Response Report			
ΓΑ/Ι Approved: Yes No Date Approved: Priority: - Select -			
TA/I Lead: , Phone () - , x			
ection 5: ITA/I Lead Planning, Conduct, and Reporting			
lan Development Start Date:			
TA/I Plan # NESC-PL-			
lan Approval Date:			
ΓΑ/I Start Date Planned: Actual:			
ΓΑ/I Completed Date:			
ITA/I Final Report #: NESC-PN-			
ITA/I Briefing Package #: NESC-PN-			
Follow-up Required? Yes No			
ection 6: Follow-up			
Pate Findings Briefed to Customer:			
ollow-up Accepted: Yes No			
ollow-up Completed Date:			
ollow-up Report #: NESC-RP-			
ection 7: Disposition and Notification			
Totification type: - Select - Details:			
Date of Notification:			
Final Disposition: - Select -			
ationale for Disposition:			
Close Out Review Date:			

	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0		
Title:			Page #:		
Kenn	edy Space Center (KSC) Launch Complex	39 (LC-	23 of 32		
39	39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior				
Predi	Prediction Model Review Technical Assessment Report				

Form Approval and Document Revision History

Approved:		
••	NESC Director	Date

Version	Description of Revision	Office of Primary Responsibility	Effective Date
1.0	Initial Release	Principal Engineers Office	29 Jan 04

To the second se	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0
39)	edy Space Center (KSC) Launch Complex Gaseous Hydrogen (GH ₂) Vent Arm Beh ction Model Review Technical Assessmen	avior	Page #: 24 of 32

Appendix B. Vent Pipe Sensitivities




Figure B.1. End of Vent Arm as it Enters Deceleration Unit

Model contains post STS-108 update to the Structure and a horizontal clearance of 19.07".

The state of the s	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0
39	edy Space Center (KSC) Launch Complex) Gaseous Hydrogen (GH ₂) Vent Arm Beh ction Model Review Technical Assessmen	avior	Page #: 25 of 32




Figure B.2. Pivot Arm Flexure Sensitivity

End of vent arm clearance with the Deceleration Unit when the pivot arm is flexed 3 degrees from joint with FSS and joint with Slider Block. Clearance is reduced from 19.07" to 10.5" on the modified Deceleration Unit.

10	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0
39)	edy Space Center (KSC) Launch Complex Gaseous Hydrogen (GH2) Vent Arm Beh ction Model Review Technical Assessmen	avior	Page #: 26 of 32




Figure B.3. Joint Stop Sensitivity

End of arm clearance with the Deceleration Unit when the two joints between the pivot arm and the Slider Block and the Slider Block and the Trunnions have a combined slope equal to one degree. Clearance is reduced from 19.07" to 14.41" on the modified Deceleration Unit.

TO STATE OF THE PARTY OF THE PA	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0		
Title:					
Kennedy Space Center (KSC) Launch Complex 39 (LC-					
39)	39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior				
Predi	Prediction Model Review Technical Assessment Report				

Appendix C. Pictures of the FE Model and the Associated Calculations



NASA Engineering and Safety Center Technical Assessment Report

Document #: RP-05-114 Version: 1.0

Page #: 28 of 32

Kennedy Space Center (KSC) Launch Complex 39 (LC-39) Gaseous Hydrogen (GH₂) Vent Arm Behavior **Prediction Model Review Technical Assessment Report**

M. Ian Johnston

7/15/2005

Page 1 of 3



Marshall Space Flight Center ER41 - Structural & Dynamics Analysis Branch

CMM 234 - Review

Vent Pipe Stiffness Calculations

Length of vent arm:

$$L_{pipe} := 275 \cdot in$$

Inner pipe (8" Sch. 5)

$$ID_8 := 8.407 \cdot in$$

$$A_8 := \frac{\pi}{4} \cdot (OD_8^2 - ID_8^2)$$
 $A_8 = 2.916 \text{ in}^2$

$$A_R = 2.916 \text{ in}^2$$

$$I_8 := \frac{\pi}{64} \cdot \left(OD_8^4 - ID_8^4\right)$$
 $I_8 = 26.44 \text{ in}^4$

$$I_{\Omega} = 26.44 \, \text{in}^4$$

Outer pipe (10" Sch. 10)

$$A_{10} := \frac{\pi}{4} \cdot \left(OD_{10}^2 - ID_{10}^2\right)$$
 $A_{10} = 5.487 \text{ in}^2$

$$A_{10} = 5.487 \text{ in}^2$$

$$I_{10} := \frac{\pi}{64} \cdot \left(OD_{10}^{4} - ID_{10}^{4}\right)$$
 $I_{10} = 76.864 \text{ in}^{4}$

Combined Area's and Moments of Inertia

$$I_c := I_{10} + I_8$$

$$I_c = 103.304 \text{ in}^4$$

$$A_c := A_{10} + A_8$$

$$A_c = 8.403 \text{ in}^2$$

Data from hand calculations:

$$E_{steel} := 29000 \cdot ksi$$

$$k_{hand} \coloneqq \frac{3 \cdot E_{steel} \cdot I_c}{L_{pipe}^{-3}}$$

$$k_{\mathbf{hand}} = 432.154 \, \frac{\mathbf{lbf}}{\mathbf{in}}$$

(cantilever pipe with point load at end)

Data used in Adams Model

per Roy Burton e-mail

per Roy Burton e-mail

$$v_{pipe} := \frac{E_{pipe}}{2 \cdot G_{pipe}} - 1$$

 $v_{pipe} = 0.3$

Poisson's Ratio

per Roy Burton e-mail

$$k_{roy} := \frac{3 \cdot E_{pipe} \cdot I_{roy}}{L_{pine}^{3}}$$

$$k_{roy} = 348.801 \frac{lbf}{in}$$

$$diff_{pipe} := \frac{k_{hand} - k_{roy}}{mean(k_{hand}, k_{roy})}$$

$$diff_{pipe} = 21.346\%$$



NASA Engineering and Safety Center Technical Assessment Report

Document #: RP-05-114 Version: 1.0

Page #: 29 of 32

Kennedy Space Center (KSC) Launch Complex 39 (LC-39) Gaseous Hydrogen (GH₂) Vent Arm Behavior **Prediction Model Review Technical Assessment Report**

> M. lan Johnston 7/15/2005

Page 2 of 3



Marshall Space Flight Center ER41 - Structural & Dynamics Analysis Branch

CMM 234 - Review

Pivot Arm Stiffness Calculations

M := 18000 · in · lbf Moment applied to FEM about y-axis

Compute K₁ from Finite Element Model (Stiffness between pivot and shock interface)

Node Number (at shock interface location)

Rotational displacement about y-axis from FEM results

Node 7641

 $\theta_{y_{7641}} := 2.943 \cdot 10^{-3} \cdot rad$

 $\theta y_{7641} = 0.169 \text{ deg}$

Node 9079

 $\theta y_{9079} := 2.941 \cdot 10^{-3} \cdot rad$ $\theta y_{9079} = 0.169 \text{ deg}$

$$K_1 := \frac{M}{\text{mean}(\theta y_{7641}, \theta y_{9079})}$$
 $K_1 = 1.068 \times 10^5 \frac{\text{in-lbf}}{\text{deg}}$

$$K_1 = 1.068 \times 10^5 \frac{\text{in · lbf}}{\text{deg}}$$

Section 1 stiffness

$$K1_{cmm234} := 1.576 \cdot 10^5 \cdot \frac{\text{in · lbf}}{\text{deg}}$$

Stiffness used in CMM 234

$$\operatorname{diff}_1 := \frac{\operatorname{Kl}_{\operatorname{cmm234}} - \operatorname{K}_1}{\operatorname{mean}(\operatorname{K}_1, \operatorname{Kl}_{\operatorname{cmm234}})}$$

$$diff_1 = 38.4\%$$

Compute Kt from Finite Element Model (Stiffness of entire pivot arm)

Node Number (at trunnion location)

Rotational displacement about y-axis from FEM results

Node 15742

 $\theta y_{15742} := 9.687 \cdot 10^{-3} \cdot rad$ $\theta y_{15742} = 0.555 deg$


Node 15743

 $\theta y_{15743} := 9.687 \cdot 10^{-3} \cdot rad$ $\theta y_{15743} = 0.555 deg$

$$K_{t} := \frac{M}{\text{mean}(\theta y_{15742}, \theta y_{15743})} \qquad K_{t} = 3.243 \times 10^{4} \frac{\text{in·lbf}}{\text{deg}}$$

$$K_t = 3.243 \times 10^4 \frac{\text{in · lbf}}{\text{dag}}$$

Overall stiffness





Marshall Space Flight Center ER41 - Structural & Dynamics Analysis Branch

M. Ian Johnston 7/15/2005 Page 3 of 3

CMM 234 - Review

Compute K2 (Stiffness between shocks and trunnion)

Compute second section stiffness using the following relationship.

$$\frac{1}{K_t} = \frac{1}{K_1} + \frac{1}{K_2}$$

for springs in series

$$\kappa_2 := -\kappa_t \cdot \frac{\kappa_1}{-\kappa_1 + \kappa_t}$$

$$K_2 = 4.658 \times 10^4 \frac{\text{in lbf}}{\text{deg}}$$

Section 2 stiffness

$$K2_{cmm234} := 5.7065 \cdot 10^4 \cdot \frac{\text{in · lbf}}{\text{deg}}$$

Stiffness used in CMM 234

$$diff_2 := \frac{K2_{cmm234} - K_2}{mean(K_2, K2_{cmm234})}$$

 $diff_2 = 20.2\%$




Figure 1: Pivot Arm FE Model

	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0		
Title:			Page #:		
Kenn	31 of 32				
39	39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior				
Predi	Prediction Model Review Technical Assessment Report				

Appendix D. List of Acronyms

ASCE American Society of Civil Engineering

AT Analytical Tool ET External Tank FE Finite Element

FSS Fixed Support System GH₂ Gaseous Hydrogen

GUCP Ground Umbilical Carrier Panel

HPAS Haunch Pivot Arm Slot
KSC Kennedy Space Center
LC-39 Launch Complex 39
LCC Launch Commit Criteria
MSFC Marshall Space Flight Center

NASA National Aeronautics and Space Administration

NCE NESC Chief Engineer

NESC NASA Engineering and Safety Center

NW Northwest SE Southeast

SRB Solid Rocket Booster
SSME Space Shuttle Main Engine
SSP Space Shuttle Program
USA United Space Alliance

	NASA Engineering and Safety Center Technical Assessment Report	Document #: RP-05-114	Version: 1.0	
Title:				
Kennedy Space Center (KSC) Launch Complex 39 (LC-				
39) Gaseous Hydrogen (GH ₂) Vent Arm Behavior				
Predi	ction Model Review Technical Assessment	t Report		

Approval and Document Revision History

Approved:	Original signed on file	10/17/05
	NESC Director	Date

Version	Description of Revision	Office of Primary Responsibility	Effective Date
1.0	Initial Release	NESC Chief Engineer's Office	10/17/05

REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

The public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.

valid OMB control number. PLEASE DO NOT RETURN YOUR FORM TO	THE ABOVE ADDRESS.		
	2. REPORT TYPE		3. DATES COVERED (From - To)
01-03-2009	Technical Memorandum		March 2005- October 2005
4. TITLE AND SUBTITLE		5a. CON	TRACT NUMBER
Kennedy Space Center (KSC) Launch Complex 39 (LC-39) Gaseous Hydrogen (GH2) Vent Arm Behavior Prediction Model Review Technical Assessment Report			NT NUMBER
		5c. PRO	GRAM ELEMENT NUMBER
6. AUTHOR(S)		5d. PRO	JECT NUMBER
Wilson, Timmy R.; Beech, Geoffrey; Johnston, Ian.		5e. TASI	(NUMBER
		5f. WOR	K UNIT NUMBER
			510505.01.07.01.06
7. PERFORMING ORGANIZATION NA NASA Engineering and Safety Cer Langley Research Center Hampton, VA 23681-2199	` ,		8. PERFORMING ORGANIZATION REPORT NUMBER L-19605 NESC-RP-05-114/05-013-E
9. SPONSORING/MONITORING AGEI	NCY NAME(S) AND ADDRESS(ES)		10. SPONSORING/MONITOR'S ACRONYM(S)
National Aeronautics and Space Administration Washington, DC 20546-0001			NASA
11 dolling con, 2 0 200 10 0001			11. SPONSORING/MONITORING REPORT NUMBER
			NASA/TM-2009-215570

12. DISTRIBUTION/AVAILABILITY STATEMENT

Unclassified - Unlimited Subject Category 20 Spacecraft Propulsion And Power

13. SUPPLEMENTARY NOTES

14. ABSTRACT

The NESC Assessment Team reviewed a computer simulation of the LC-39 External Tank (ET) GH2 Vent Umbilical system developed by United Space Alliance (USA) for the Space Shuttle Program (SSP) and designated KSC Analytical Tool ID 451 (KSC AT-451). The team verified that the vent arm kinematics were correctly modeled, but noted that there were relevant system sensitivities. Also, the structural stiffness used in the math model varied somewhat from the analytic calculations. Results of the NESC assessment were communicated to the model developers.

15. SUBJECT TERMS

ET, GH2, GUCP, LC-39, SSP

16. SECURITY	16. SECURITY CLASSIFICATION OF:		17. LIMITATION OF ABSTRACT	18. NUMBER OF	19a. NAME OF RESPONSIBLE PERSON
a. REPORT	b. ABSTRACT	c. THIS PAGE		PAGES	STI Help Desk (email: help@sti.nasa.gov)
****	****	****	UU	27	19b. TELEPHONE NUMBER (Include area code)
UU	UU	UU		37	(443) 757-5802